

**NATIONAL LAW INSTITUTE UNIVERSITY**  
Kerwa Dam Road, Bhopal-462044

Phone: (0755)- 2696777(O)

Fax: (0755)- 2696965 (O)

e-mail: info@nliu.com

Web: www.nliu.ac.in

Ref. No. 3668/NLIUB

Dated: 18/08/2022

**NOTIFICATION**

Sealed quotations are invited by the Registrar on behalf of the University for the Work of Repair and service of Solar Water Heater. The agency shall visit the site before quote and the agency shall quote their rates inclusive materials, labour and taxes complete in all respect in the prescribed format as given below. The agency shall submit their sealed quotation in the envelop and mention the name of work. The agency shall enclose the copy of PAN NO and GST NO along with quotation on before 28/08/2022 during office hours up to 5.0 P.M in the office of National Law Institute University, Kerwa Dam Road, Bhopal- 462044. The agency shall send their quotation by post and the same shall be received on or before 28/08/2022 up to 5.0 PM, the University not responsible for any postal delay. The agency shall download the prescribed format our website:www.nliu.ac.in.

  
(Assistant Registrar)

## **SCOPE OF WORK:**

### **Old Boys Hostel Building: -**

- 1) Four nos. of Evacuated Tube Collectors of 500 LPD Solar Water Heating Systems are Broken.

### **New Boys Hostel Building: -**


- 1) Two nos. of Evacuated Tube Collectors of 500 LPD Solar Water Heating Systems are Broken.
- 2) One no of 500 LPD Old Solar Water Heating System is totally damage which is mrepairable.
- 3) Air vent of one no of Solar Water Heating System is broken.

### **Old Girls Hostel Building: -**

- 1) In Three nos. of 500 LPD Solar Water Heating Systems Total 15 nos of Evacuated tube collectors are broken.

### **Guest House Building: -**

- 1) One nos. of 500 LPD Solar Water Heating System T-Glass has come out from the collector and one leg of the collector is broken.
- 2) Air vent of one no of Solar Water Heating System is broken.



## BILL OF QUANTITIES

S.NO	DESCRIPTION	QTY.	RATE	AMOUNT
1	Evacuated Tube Collectors of 500 LPD Solar Water Heating Systems	21		
2	Air vent of one no of Solar Water Heating System alongwith required necessary plumbing fittings.	2		
3	Replacement of one no of totally damage Solar Water Heating System which is non repairable with the new one	1		
	TOTAL			

### Terms and conditions:-

1. Agency shall quote their rates inclusive of GST.
2. Delivery/work completion period one – two weeks.
3. Payment 100% after completion of work.

(Signature of bidder)  
with seal

